




1/8



Not approved  
by Y2



5/8




FIG.12




FIG.13

Not Approved  
AC/SL



6/8




FIG. 14

approved  
D.K.Y.



7/8




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20




FIG. 21

Approved  
M. J. H.

4/8




FIG. 7




FIG. 8




FIG. 9




FIG. 10

Not Approved  
BEP2



WO 99/44187

PCT/FR99/00421




FIG.22




FIG.23




FIG.24




FIG.25





FIG.26




FIG.27




FIG.28